From: Janet Way
To: City Council

Subject:Soil conditions on 145th CorridorDate:Monday, April 11, 2016 7:00:00 PM

Attachments: mms img-1847639761.jpg

 $\underline{\mathsf{ATT00002}.\mathsf{txt}}$ 

## Dear Council,

This is an example of the soil conditions within about 100ft of 145th. The old power pole here on 148th and Ninth Place was removed last fall. The neighbors and workers observed that it filled up with water immediately due to the very high water table. Ever since, they keep filling it with dirt every few weeks and it sinks.

This is an example of potential problems in this FEMA "liquefaction zone" next to the 145th corridor.

